



- 1** Della V.Wright No.2 Wabash Twp., Sec.9, T.1 N.R.12 W.
- 2** Della V.Wright No.1 Wabash Twp., Sec.9, T.1 N.R.12 W.
- 3** McMillen Farm No.6 S.E.1/4 N.E.1/4, Sec.9, T.1 N.,R.12 W.
- 4** Caroline Smith No.2 Wabash Twp., Sec.9, T.1 N.,R.12 W.
- 5** Caroline Smith No.1 Wabash Twp., Sec.9, T.1 N.,R.12 W.
- 6** H.Buchanan No.1 N.W.Cor., S.W.1/4, Sec.10, Wabash Twp.

East-west cross-section through Allendale field showing position of oil sand

The thick limestones shown in the lower part of the coal-bearing rocks in 3 and 5 were probably incorrectly reported by the driller. They should probably be shown as sandstone or sandy shale.